



(1.2162) Thermal Cycle Diagram


In certain cases intermediate annealing or isotherm transformation may be useful depending on the tool or component. Please contact us.



Continuous Cooling Transformation Diagram (CCT) (core area)



Tempering Diagram (for carburized surface)



Remarks: All technical information is for reference only.